

Visitor Access Safety Requirements for Westinghouse Warrendale Facility

Welcome to the GICP Manufacturing and Test facility (known as the GICP Shop). The GICP Shop is a 10CFR50 Appendix B Supplier of Safety Hardware, System Integration and Testing. In addition, the GICP Shop has expanded to include a commercial process that allows the same space and technical staff to build Non-Safety Hardware, System Integration and Testing. Most of the products built and tested at GICP is related to Instrumentation and Control Systems that operate and maintain safety at Nuclear Power plants. This includes cables, small I/O devices, larger electronics units and PLC hardware, and up to full height cabinets containing all the subassemblies built and tested in support of the total system design. Safety is our number 1 priority along with Quality and Cost.

The following criteria for entry at Warrendale and general work practices will apply:

- 1. Wear your identification credential at all times. This credential identifies you for security purposes.
- 2. Remain with your escort at all times. You must maintain continuous visual contact with your escort. The exception is when you go to the restroom.
- 3. Do not enter areas posted where electrical or other hazardous work is taking place, observe all signs and barricades, unless specifically authorized by responsible Westinghouse personnel.
- 4. Review the alarms, evacuation and accountability requirements with your escort. All personnel must evacuate the facility as directed during emergency situations.
- 5. Obey all safety rules and signs. Safety glasses and closed toe, closed heel shoes are required on the shop floor. The office does not have any specific PPE requirements.
- 6. Drinking (unless in a closed container) and using tobacco products are prohibited on the shop floor. Eating is permitted in the kitchen area, at an employee desk or cubicle, or at work benches that do not contain deliverable work in progress or materials.
- 7. All emergencies shall be reported to Security by calling 412-374-2090, or simply picking up any red phone on the shop floor.
- 8. Injuries shall be reported to your Westinghouse escort immediately.
- 9. First aid kits and AED's are available and used by Security if needed.
- 10. Emergency stops are located throughout the shop floor and are labeled with what equipment it powers down.

While visiting the Westinghouse Warrendale site, you are required to follow all Westinghouse policies and procedures. Failure to adhere to these policies and procedures can result in denial of access to the site. Your site escort will notify you of any hazardous work taking place during your visit and any additional safety requirements that need to be adhered to.